



Extinguisher shows signs of corrosion in several parts.



Connection hole to the pressure cylinder/valve.

Part of the victim's finger.



Pressure cylinder/valve with signs of corrosion.



Training area and the victim.



Training area and the victim after the accident.



Death was caused by injuries on the victim's neck and face.



Extinguisher bottom was found far away from the accident site.

